

& coolkidsbouncycastleles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2287

Structure	P	F	N/A
Security of Seams	✓		
Stitching	✓		
Anchor Points	✓		
Anchor Accessories	✓		
Walls & Towers	✓		
Blower Distance	✓		
Zip(s)	✓		
Fabric Flame Retardant	✓		
Fabric Strength	✓		
Step/Ramp Size	✓		
Grounding	✓		
Sharp Angles & Edges	✓		
Stability	✓		
Ropes	✓		
Artwork to EN71-3? (Supplier/Importer must provide certificates for new equipment)			✓
Air Loss Points	✓		
Water Gauge Pressure	✓		
Fall Off Height	✓		
Trough Depth	✓		
Thread	✓		
Netting	✓		
Entrapment	✓		
Deflation/Evacuation Time	✓		
Windows			✓
Markings	✓		
Identification	✓		

Totally Enclosed Structures

Exits
Exit Markings
Lighting Supports
Emergency Lighting
Deflation Speed
User Area Pressure

Slides

Wall Heights
Run Out
Clamber Net
Slide Sheet

Blower

Size & Type	✓		
Inlet & Outlet Mesh	✓		
Cable & Plug	✓		
Casing & Impeller	✓		
Pat Test	✓		
Return Flap	✓		

Manufactured by:

Serial Number

Year Made:

Description of Unit:

Colour:

Size:

Max No. Users:

Max User Height:

Date Issued:

Expiry Date:

Notes/Risk Assessment

1. All Bungee Ropes CHANGED AT TIME OF TEST
2. WEAR AROUND HOLDS THAT THE BUNGE ROPE FISH THROUGH
3. NOTHING MEANT TO BE ATTACHED TO BUNGE CORDS ON OUTSIDE TOWERS
4. GIBBS IS SHOWN BLOWN HSPLOD

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:

Print: